

Standard Checklist

Name of Riparian-Wetland Area: Hitchcock Creek

Date: May 27, 2004

Segment/Reach ID: Reach 10

PFC 310

Miles: _____ Elevation: 369 GPS: N 36, 27. 976' W 121, 43. 427'

ID Team Observers: Clive Sanders, Danica Zupic

Time: 1:20 pm

Yes	No	N/A	HYDROLOGY
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	1) Floodplain above bankfull is inundated in "relatively frequent" events
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	2) Where beaver dams are present they are active and stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>		3) Sinuosity, width/depth ratio, and gradient are in balance with the landscape setting (i.e., landform, geology, and bioclimatic region)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	4) Riparian-wetland area is widening or has achieved potential extent
<input type="checkbox"/>	<input checked="" type="checkbox"/>		5) Upland watershed is not contributing to riparian-wetland degradation

Yes	No	N/A	VEGETATION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	6) There is diverse age-class distribution of riparian-wetland vegetation (recruitment for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7) There is diverse composition of riparian-wetland vegetation (for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	8) Species present indicate maintenance of riparian-wetland soil moisture characteristics
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9) Streambank Vegetation is comprised of those plants or plant communities that have root masses capable of withstanding high-streamflow events
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10) Riparian-wetland plants exhibit high vigor
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11) Adequate riparian-wetland vegetative cover is present to protect banks and dissipate energy during high flows
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	12) Plant communities are an adequate source of coarse and/or large woody material (for maintenance/recovery)

Yes	No	N/A	EROSION/DEPOSITION
<input checked="" type="checkbox"/>	<input type="checkbox"/>		13) Floodplain and channel characteristics (i.e., rocks, overflow channels, coarse and/or large woody material) are adequate to dissipate energy
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14) Point bars are revegetating with riparian-wetland vegetation
<input checked="" type="checkbox"/>	<input type="checkbox"/>		15) Lateral stream movement is associated with natural sinuosity
<input type="checkbox"/>	<input checked="" type="checkbox"/>		16) System is vertically stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>		17) Stream is in balance with the water and sediment being supplied by the watershed (i.e., no excessive erosion or deposition)

Summary Determination

Functional Rating:

Proper Functioning Condition
Functional—At Risk
Nonfunctional
Unknown

<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Trend for Functional—At Risk:

Upward
Downward
Not Apparent

<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes
No


<input checked="" type="checkbox"/>
<input type="checkbox"/>

If yes, what are those factors?

- | | | |
|---|--|--|
| <input type="checkbox"/> Flow regulations | <input type="checkbox"/> Mining activities | <input type="checkbox"/> Upstream channel conditions |
| <input type="checkbox"/> Channelization | <input type="checkbox"/> Road encroachment | <input type="checkbox"/> Oil field water discharge |
| <input type="checkbox"/> Augmented flows | <input checked="" type="checkbox"/> Other (specify) <u>Natural steep banks</u> | |



Picture 1



Picture 2



Picture 3

Remarks

The vegetation is diverse in both age- class and composition. The area is wet from seepage and has a lot of algae growing in the creek bed (See Picture 3).

There are two upland hillsides that are eroding and contributing sediment to the reach but there is no excessive deposition (See Picture 1 and 2) . There is evidence of some erosion throughout the creek bed where tree and vine roots have been partially exposed.

There are a few banks that have been stabilized with sandbags, however, the sandbags are deteriorating.

Yard waste has been dumped in three different sites in the creek (See Picture 2- yard debris).

A separate PFC was done for House #49 where a variety of problems inconsistent with the rest of the reach are found.

Reach ended at #54 Peacock crossing.

Checklist Comments

#5 The upland watershed is eroding at two spots and contributing sediment and there is an excess of sediment throughout the creek.

#16 The system is not stable where sandbags are degrading.