

Standard Checklist

Name of Riparian-Wetland Area: San Clemente Creek

Date: June 3, 2004 Segment/Reach ID: Reach 1, Confluence with dam PFC 601

Miles: _____ Elevation: 508 ft. GPS: N 36, 26. 031' W 121, 42. 605'

ID Team Observers: Clive Sanders, Danica Zupic Time: 11:00 am

Yes	No	N/A	HYDROLOGY
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	1) Floodplain above bankfull is inundated in "relatively frequent" events
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	2) Where beaver dams are present they are active and stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>		3) Sinuosity, width/depth ratio, and gradient are in balance with the landscape setting (i.e., landform, geology, and bioclimatic region)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	4) Riparian-wetland area is widening or has achieved potential extent
<input checked="" type="checkbox"/>	<input type="checkbox"/>		5) Upland watershed is not contributing to riparian-wetland degradation

Yes	No	N/A	VEGETATION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	6) There is diverse age-class distribution of riparian-wetland vegetation (recruitment for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7) There is diverse composition of riparian-wetland vegetation (for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	8) Species present indicate maintenance of riparian-wetland soil moisture characteristics
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9) Streambank Vegetation is comprised of those plants or plant communities that have root masses capable of withstanding high-streamflow events
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10) Riparian-wetland plants exhibit high vigor
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11) Adequate riparian-wetland vegetative cover is present to protect banks and dissipate energy during high flows
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	12) Plant communities are an adequate source of coarse and/or large woody material (for maintenance/recovery)

Yes	No	N/A	EROSION/DEPOSITION
<input type="checkbox"/>	<input checked="" type="checkbox"/>		13) Floodplain and channel characteristics (i.e., rocks, overflow channels, coarse and/or large woody material) are adequate to dissipate energy
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14) Point bars are revegetating with riparian-wetland vegetation
<input checked="" type="checkbox"/>	<input type="checkbox"/>		15) Lateral stream movement is associated with natural sinuosity
<input checked="" type="checkbox"/>	<input type="checkbox"/>		16) System is vertically stable
<input type="checkbox"/>	<input checked="" type="checkbox"/>		17) Stream is in balance with the water and sediment being supplied by the watershed (i.e., no excessive erosion or deposition)

Summary Determination

Functional Rating:

Proper Functioning Condition
Functional—At Risk
Nonfunctional
Unknown

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Trend for Functional—At Risk:

Upward
Downward
Not Apparent

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes
No

<input type="checkbox"/>
<input type="checkbox"/>

If yes, what are those factors?

Flow regulations Mining activities Upstream channel conditions
 Channelization Road encroachment Oil field water discharge
 Augmented flows Other (specify) _____

Remarks

This reach is on a sedimentation plain that has vegetated in the past 4 years. Sediment is continually added to it. The creek bed and surrounding banks are comprised of fines at least 1 foot deep in the creek bed.

There is a variety and an abundance of young trees, grasses and shrubs.

At the confluence with the reservoir, there are barren sandbars, a few dead bushes and a dozen dying Alders resulting from the dam draw down of 10 feet (See Picture 1).

There were a few steelhead fry observed.



Picture 1

Checklist Comments

#5, 17 This is a growing sedimentation plain so although there is deposition doesn't seem to be severely degrading this reach.

#9, 11, 13 Although there is a lot of growing vegetation, the trees do not have a hard substrate or bedrock to attach to. It should be noted that historically sedimentation plains are easily washed away in high flow events.