

Standard Checklist

Name of Riparian-Wetland Area: Garzas Creek

Date: August 6, 2004 Segment/Reach ID: Reach 4 PFC 801

Miles: _____ Elevation: _____ GPS: N 36, 29. 342' W 121, 45. 081'

ID Team Observers: Clive Sanders, Danica Zupic Time: _____

Yes	No	N/A	HYDROLOGY
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	1) Floodplain above bankfull is inundated in "relatively frequent" events
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	2) Where beaver dams are present they are active and stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>		3) Sinuosity, width/depth ratio, and gradient are in balance with the landscape setting (i.e., landform, geology, and bioclimatic region)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	4) Riparian-wetland area is widening or has achieved potential extent
<input checked="" type="checkbox"/>	<input type="checkbox"/>		5) Upland watershed is not contributing to riparian-wetland degradation

Yes	No	N/A	VEGETATION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	6) There is diverse age-class distribution of riparian-wetland vegetation (recruitment for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7) There is diverse composition of riparian-wetland vegetation (for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	8) Species present indicate maintenance of riparian-wetland soil moisture characteristics
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9) Streambank Vegetation is comprised of those plants or plant communities that have root masses capable of withstanding high-streamflow events
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10) Riparian-wetland plants exhibit high vigor
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11) Adequate riparian-wetland vegetative cover is present to protect banks and dissipate energy during high flows
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	12) Plant communities are an adequate source of coarse and/or large woody material (for maintenance/recovery)

Yes	No	N/A	EROSION/DEPOSITION
<input checked="" type="checkbox"/>	<input type="checkbox"/>		13) Floodplain and channel characteristics (i.e., rocks, overflow channels, coarse and/or large woody material) are adequate to dissipate energy
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14) Point bars are revegetating with riparian-wetland vegetation
<input checked="" type="checkbox"/>	<input type="checkbox"/>		15) Lateral stream movement is associated with natural sinuosity
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	16) System is vertically stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>		17) Stream is in balance with the water and sediment being supplied by the watershed (i.e., no excessive erosion or deposition)

Summary Determination

Functional Rating:

Proper Functioning Condition
Functional—At Risk
Nonfunctional
Unknown

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Trend for Functional—At Risk:

Upward
Downward
Not Apparent

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes
No

<input type="checkbox"/>
<input type="checkbox"/>

If yes, what are those factors?

<input type="checkbox"/> Flow regulations	<input type="checkbox"/> Mining activities	<input type="checkbox"/> Upstream channel conditions
<input type="checkbox"/> Channelization	<input type="checkbox"/> Road encroachment	<input type="checkbox"/> Oil field water discharge
<input type="checkbox"/> Augmented flows	<input type="checkbox"/> Other (specify) _____	



Picture 1



Picture 2



Picture 3

Remarks

This reach begins at E. Garzas Road Bridge 506 and goes to the confluence of Garzas Creek with the Carmel River.

This reach was rated in PFC due to the presence of mature Cottonwoods, Willows, Laurels and their recruits. The creek bed is ideally composed of cobbles, rocks, gravel and fines.

There is one large fallen cottonwood tree that needs to be removed (See Picture 1).

The southern bank has stacked yard waste that needs to be removed (See Picture 2).

There are remnants of an old concrete bridge just downstream from the existing county bridge.

There are two dirt piles on private property that are near a side channel of the creek that need to be moved (See Picture 3).

Despite these removals the creek has plenty of LWD, vigorous mature trees and groundcover to properly dissipate energy and sediment.

This reach ended at the confluence with the Carmel River (See Picture 4).

GPS: N36,29.538 W121,45.054 Elevation 229

Checklist Comments

None - The System is in PFC



Picture 4