

Standard Checklist

Name of Riparian-Wetland Area: Garzas Creek

Date: June 23, 2004 Segment/Reach ID: Reach 3 (Anecdotal) PFC 802

Miles: _____ Elevation: 213 ft GPS: N 36, 29. 153' W 121, 45. 351'

ID Team Observers: Danica Zupic Time: 5 pm

Yes	No	N/A	HYDROLOGY
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	1) Floodplain above bankfull is inundated in "relatively frequent" events
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	2) Where beaver dams are present they are active and stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>		3) Sinuosity, width/depth ratio, and gradient are in balance with the landscape setting (i.e., landform, geology, and bioclimatic region)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	4) Riparian-wetland area is widening or has achieved potential extent
<input checked="" type="checkbox"/>	<input type="checkbox"/>		5) Upland watershed is not contributing to riparian-wetland degradation

Yes	No	N/A	VEGETATION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	6) There is diverse age-class distribution of riparian-wetland vegetation (recruitment for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7) There is diverse composition of riparian-wetland vegetation (for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	8) Species present indicate maintenance of riparian-wetland soil moisture characteristics
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9) Streambank Vegetation is comprised of those plants or plant communities that have root masses capable of withstanding high-streamflow events
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10) Riparian-wetland plants exhibit high vigor
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11) Adequate riparian-wetland vegetative cover is present to protect banks and dissipate energy during high flows
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	12) Plant communities are an adequate source of coarse and/or large woody material (for maintenance/recovery)

Yes	No	N/A	EROSION/DEPOSITION
<input checked="" type="checkbox"/>	<input type="checkbox"/>		13) Floodplain and channel characteristics (i.e., rocks, overflow channels, coarse and/or large woody material) are adequate to dissipate energy
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14) Point bars are revegetating with riparian-wetland vegetation
<input checked="" type="checkbox"/>	<input type="checkbox"/>		15) Lateral stream movement is associated with natural sinuosity
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	16) System is vertically stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>		17) Stream is in balance with the water and sediment being supplied by the watershed (i.e., no excessive erosion or deposition)

Summary Determination

Functional Rating:

Proper Functioning Condition
Functional—At Risk
Nonfunctional
Unknown

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Trend for Functional—At Risk:

Upward
Downward
Not Apparent

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes
No

<input type="checkbox"/>
<input type="checkbox"/>

If yes, what are those factors?

Flow regulations Mining activities Upstream channel conditions
 Channelization Road encroachment Oil field water discharge
 Augmented flows Other (specify) _____

Remarks

This reach was assessed through anecdotal observations by Clive Sanders on previous fish rescues. This reach is in PFC. The vegetation is both diverse in composition and age class. The banks have a little erosion although it is to a natural degree. There is LWD in the creek that is properly dissipating energy and is not excessive. There are plenty of rocks and cobbles to provide steelhead with proper rearing and spawning habitat. The house is far enough from the bank that its foundation and garden do not impact the creek.

There is a summer dam which has been recently modified to ensure fish passage. The pool provides a haven for steelhead young of the year that proceed downstream as the creek dries up.

This reach ended at County Bridge 506 on E. Garzas Road.
GPS: N36,29.342 W121,45.081

Checklist Comments

#12 There is a perfect amount of LWD for energy dispersal, and fish habitat.