


**Figure IX-4**  
**Daily Count of Adult Steelhead Passing the San Clemente Dam Fish Ladder**  
**Compared to Daily Flow Downstream of the Ladder During the 2005 – 2006 Migration Season**



\*\* Streamflow measured at MPWMD gaging station at Sleepy Hollow Weir or San Clemente Spillway